50 Um:

Each

: WEARPLATE

: D2577 REV E

: D25773

: N/A

:NIA

: 08/08/2006

: E

Date:

Friday, 21/07/2006 12:00:47 PM

Linda Lacelle

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 28013

Estimate Number

: 10298

P.O. Number This Issue

: NIA

Prsht Rev. First Issue

Previous Run

: 21/07/2006

: NC

: N/A

: PURCHASED PARTS

: 28013

Written By

Checked & Approved By

Comment

: Est:

F 02.09.24

S.O. No. : NA

Re-format; Incorporated D2577-101/-13 KJ/

EC

Est. C 06.07.21

wateriet

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

M1010S16GA

1010/1025/A21/6aA SHEET



Comment: Qty.:

0.9240 sf(s)/Unit Total: 46.2000 sf(s)

0.063 thick

1010/1025/A21/6aA SHEET

Batch: M101463

2.0

WATER JET



1-Cut as per Dwg D2577

Dwg Rev:

Prog Rev:

2-Deburr if necessary

3.0

QC2



Comment: INSPECT PARTS AS THEY COME OFF, MACHINE



QC8

SECOND CHECK

4.0

Comment: SECOND CHECK

5.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Deburr

Friday, 21/07/2006 12:00:48 PM Date: User: Linda Lacelle **Process Sheet** Drawing Name: WEARPLATE Customer: CU-DAR001 Dart Helicopters Services Job Number: 28013 Part Number: D25773 Job Number: Seq. #: Description: Machine Or Operation: NC BRAKE 6.0 BRAKE NC Comment: NC BRAKE 26/08/14 SC 1-Form on brake as per Dwg D2577 using DT8155 and DT8179 2-Identify as D2577-3 INSPECT WORK TO CURRENT STEP 7.0 QC5 Comment: INSPECT WORK TO CURRENT STEP LARGE FAB 1 8.0 LARGE FABRICATION RESOURCE 1 **Comment: LARGE FABRICATION RESOURCE 1** Weld hard surface using DT8308A & DT8308B as per Dwg D2577 Qty Description Batch A/R 7560 Hardcoat Rod M10078C 9.0 QC9 **Comment: VISUAL WELDING INSPECTION** 10.0 POWDER COATING POWDER COATING Comment: POWDER COATING Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3 INSPECT POWDER COAT/CHEMICAL CONVERSION 11.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION PACKAGING RESOURCE #1 PACKAGING 1 12.0 Comment: PACKAGING RESOURCE #1 Identify and Stoo Location: 13.0 DC DOCUMENT CONTROL Comment: DOCUMENT CONTROL Inspection Level 21 Page 2

Qty:

50 Um:

Each

: WEARPLATE

: D2577 REV E

: D25773

: 8/8/2006

: N/A

; E

Date:

Friday, 7/21/2006 7:36:52 AM

: 26058

User:

Kim Johnston

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

Customer

: CU-DAR001 Dart Helicopters Services

Type

S.O. No. :

Job Number : 28013 **Estimate Number** : 10298

P.O. Number

: 7/21/2006 This Issue

Prsht Rev. : NC

: // First Issue

Previous Run

Written By

Comment

Checked & Approved By

: Est:

Re-format; Incorporated D2577-101/-13 KJ/

: PURCHASED PARTS

RF

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description: **PURCHASING**

1.0 PG



Comment: PURCHASING

Issue P/O:

Email or Ship DXF file to vendor

Laser Cut per Dwg D2577 flat pattern D2577-101

Material release note required

2.0 D25773F Wearplate Aft



1.0000 U(s)/Unit Total:

50.0000 U(s)



PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1 Receive & Inspect For Transit Damage

Ensure material release note is attached 4.0 QC6

DIMENSIONAL CHECK



Comment: DIMENSIONAL CHECK

Inspect dimensions per template D2577-101T

5.0

3.0

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Deburr



Form: rprocess

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
3+							

NCR:	WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B	Verification	Approval	Approval		
DATE	STEP	Section A	Initial Action Description Sign & Design Mgr Date			Section C	Design Mgr	QC Inspector	
06:05:07	8	1 part scrup. Used for welch lest.	Dan	Oty 49. destroy Sample.	M.F.		1 de la companya della companya della companya de la companya della companya dell	0600,07	
						10608-07		0602.07	
				*					
				**					

Part No:	PAR #:	Fault Category: NO	CR:	Yes No DQA:	Date: 06/09/27
NOTE: Date & initial all entries				QA: N/C Closed:	Date:

Date: Friday, 7/21/2006 7:36:52 AM User: Kim Johnston **Process Sheet Drawing Name: WEARPLATE** Customer: CU-DAR001 Dart Helicopters Services Job Number: 28013 Part Number: D25773 Job Number: Seq. #: Description: **Machine Or Operation:** BRAKE NC NC BRAKE 6.0 Comment: NC BRAKE 1-Form on brake as per Dwg D2577 using DT8155 and DT8179 2-Identify as D2577-3 QC5 INSPECT WORK TO CURRENT STEP 7.0 Comment: INSPECT WORK TO CURRENT STEP LARGE FAB 1 LARGE FABRICATION RESOURCE 1 8.0 Comment: LARGE FABRICATION RESOURCE 1 Weld hard surface using DT8308A & DT8308B as per Dwg D2577 Batch Qty Description A/R 7560 Hardcoat Rod 9.0 QC9 VISUAL WELDING INSPECTION **Comment: VISUAL WELDING INSPECTION** POWDER COATING 10.0 POWDER COATING Comment: POWDER COATING Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3 11.0 INSPECT POWDER COAT/CHEMICAL CONVERSION QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 12.0 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 13.0 DC DOCUMENT CONTROL Comment: DOCUMENT CONTROL Inspection Level 21

Dart A	erospa	ce Ltd		*					
W/O:			WO	RK ORDER CHANGES	3				
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
		141							
								·	
NCR:			WORK ORDE	ER NON-CONFORMAN	CE (NCF	₹)		,	
		Corrective Action Section				Verific	-4!		
DATE	STEP	STEP Description of NC Section A	Initial Design Mgr	Action Description Design Mgr	Sign 8 Date	Section		Approval Design Mgr	Approval QC Inspector
							<u></u>		

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA	.: Date:				
NOTE: Date & initial	all entries		QA: N/C Closed	: Date:				
H:\forms\Quality Assurance	:\forms\Quality Assurance\approved forms\NCRWO revC							

Dart Aerospace Ltd


W/O:		WORK ORDER CHA	WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector			
			,							

NCR:			WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC	Description of NC Corrective Action Section B Ve			Verification	Approval	Ammanal		
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C	Approval Design Mgr	Approval QC inspector		
							25			
							A. Maria	•		
	•									
				,						
				·						
	¥									

Part No:	PAR #:	Fault Category:	NCR:	Yes	No	DQA:	 Date:	
NOTE: Date & initial all entries				QA: N	I/C C	losed:	 Date:	_

ZHS.

(TYP. 11 PLS.) WELD AFTER BENDING AS ILLUSTRATED PER DT8308



D2577-1 & D2577-3 WEARSHOE

MAKE FROM D2577-11 AND D2577-13 RESPECTIVELY POWDER COAT GREY (4.3.5.6) PER DART QSI 005 4.3 TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED








D C		œ	Α	00.09.22	DATE	CHECKED	DESIGN
98.08.17	97.05.30	96.12.04	96.09.16			APPROVED	DRAWN BY
ADD D2577-101/-11/-13	CHANGE HOLES TO OBROUNDS CORRECTED DIMENSIONS ON -1 & -3	ADD HARDCOAT WELDS	NEW ISSUE	WEARSHOE 1:10	TITLE	DRAWING NO. REV. E D2577 SHEET 1 OF 5	DART AEROSPACE LTD


D2941-300	*
SHWAYDER WEAPADS — (8 PLACES)	SECTION A-A SCALE 1:5
Γ- A \	R2.00 ~
1.50 (TYP) PATIOP COPY RETURN TO ENGINEERING ENGINEER	0.12 0.13 REMOVE POWDER COAT FROM THESE SURFACES
NOR ORDER TO WEARSHOP WATER OLLED COPY WEAR ORDER TO A MEN DO TO THOU TO A MEN DO TO THOU TO A MEN DO TO TO A MEN DO TO TO TO A MEN DO TO	SURFACES

POWDER COAT GREY (4.3.5.6) PER DART QSI 005 4.3

TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

MAKE FROM D2577-11 AND D2577-13 RESPECTIVELY





00.09.22


WEARSHOE

SHEET


4 OF 5

DRAWING NO.

D2577-7 FLAT PATTERN



D2577-7 LONGITUDINAL BEND



BREAK ALL SHARP CORNERS 0.010 TO 0.020

MATERIAL: AISI 1010-1025 OR ASTM A36/A366/A569/A570

SERIES STEEL 0.063 THICK

POWDER COAT GREY (4.3.5.6) PER DART QSI 005 4.3 FINISH: TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

UNCONTROLLED COPY D2577-7 WEARSHOE

ENGINEERING

SHOP COPY

SUBJECT TO AMENDMENT WITHOUT NOTICE WORK ORDER







DESIGN	DRAWN BY		SPACE LTD DITARIO, CANADA
CHECKED	APPROVED	DRAWING NO. D2577	REV. E SHEET 5 OF 5
DATE	<u> </u>	TITLE	SCALE
00.09.22		WEARSHOE	1:10

DETAIL B (SCALE 1:1)






DETAIL C (SCALE 1:1)



SECTION D-D (SCALE 1:1)



SHOP COPY RETURN TO **ENGINEERING** UNCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE

Copyright © 1996 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

DART AEROSPAC	E LTD	Work Order:	28013
Description:		Part Number:	D25773
Inspection Dwg:	·Rev:		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article X Prototype

Drawing	Tolerance	Actual	Accept	Reject	Method of	Comments
Dimension		Dimension		A. Africa	Inspection	
3.182	±0.010	3,175			Vern	
36.000	+ 0.010	36,000			measuring tape and vern measuring tap	
30,000	±0.010	30,005			and vern	
24.000	+0,010	24,010			measuring tape	
18000	40.016	18,008	. /		measuring tape	
12.104	t 0.010	12.110			measuring tape	
B.000	50,010	6000			measoning tape	·
2,43	20.030	2,447			Very	
2,50	7 0.030	2.53	9		Vertical	
0.220	70.010	0,220	V		Vern	
0,360	10.010	0,360			Vern	
RO. 375	10.010	RO.375	V		R-6	
0-063	\$ 0.010	0.059			Vern	
						,
		4.				
	^					
	1					
	,					
				-		
	•			4 %	14.1	

4		
Measured by: 5A1)	Audited by:	Prototype Approval:
Date: 06:08:4	Date: 06.08409	Date:

Rev	Date	Change		Revised by	Approved
Α		New Issue	,	KJ/JLM	